


Attachment F - Elevated Tank Inspection Pictures - Pages 1-6
RFx 3000021987

APPENDIX A

PHOTOGRAPHS



Tank Name Plate – good condition




Erosion of tank foundation due to family of raccoons



Roof Hatch – lid missing
Severe rusting – *This is completed 9-19-23*



Roof Vent – Good condition
Severe Rusting
Vent Screen – good condition




Lights – not working

Roof – Severe rusting and paint failure



Balcony/Shell Manway – Good condition


Severe rusting



Balcony Floor – Severe rusting and ponding water.



Balcony Railing – severe rusting




Broken Light globe located on the balcony handrails




**Riser Manway – 16" oval
Severe rusting**




Foundations with missing concrete



Exterior coating – poor condition



Interior Ceiling severe rusting



Interior Access ladder (roof to floor)
the top 10 feet are severely
deteriorated and need to be replaced



Interior Access Ladder – Deterioration



Bottom section of interior ladder –
good condition.


Severe rusting



Interior Riser – severe rusting and build up



Riser Grating – deterioration and severe rusting



Pitting located on the interior floor



Pitting located on the walls