

HVAC SHOPPING CART INVENTORY
WHOLE FACILITY
FY/SY26

Number	Site Code	FUND	Agreement Site Code	Building Name	Facility Number	System Component(s)	Model/ Serial Number
1	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 1-01	TWA09043A /20371231YA
2	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 1-02	TWA09043A/18163401YA
3	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 1-03	4TWA4048A3000AB/202451YH4F
4	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 1-04	4TWA4036A3000AB/202710W34F
5	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 1-05	4TWA4060A3000AB/2044179P2F
6	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Package Unit 1-06	YHC060F3EMA/174811178L
7	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 1-07	4TWA4048A3000AB/20406T3T4F
8	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 1-08	4TWA4048A3000AB/20341Y704F
9	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Package Unit 1-09	YSC060G3ELB03/191816875L
10	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 1-10	4TWA4048A3000AB/20341YL44F
11	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 1-11	4TWA4060A3000AB/204418C52F
12	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 1-12	4TWA4036A3000AB/20422SA54F
13	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 1-13	4TWA4036A3000AB/20422SJW4F
14	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 1-14	4TWA4036A3000AB/2027100N4F
15	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 1-15	4TWA4048A3000AB/202451T94F
16	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 2-01	TWA07243AA/20401931YA
17	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 2-02	4TWA4042A3000AB/20415K9N4F
18	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 2-03	4TWA4042A3000AB/20452UNP4F
19	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 2-04	4TWA4060A3000AB/204418BG2F
20	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 2-05	TWA07243AA/19234164YA
21	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 2-06	4TWA4048A3000AB/19491MTT4F
22	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 2-07	TWA09043AA/20371241YA
23	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 2-08	4TWA4060A3000AB/19453K9X2F
24	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 2-09	4TWA4048A3000AB/20464KBB4F
25	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 2-10	TWA07243AA/20451597YA
26	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 2-11	GAW14L24C23SA/W1C9732709
27	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 2-12	4TWA4060A3000AB/20412USN2F
28	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 2-13	4TWA4048A3000AB/20431UWP4F
29	22B91	1121025500 / 1123022100	TSC 50% - T10 50%	A100	00100	Split System 2-14	4TWA4048A3000AB/20406T114F
30	22B91	1121025500	TSC 100%	Guard House GATE # 1	00101	Split System 1-02	RX18AXVJU/K002695
31	22B91	1121025500 / 1121024300	TSC 50% - NO 50%	Telephone Office / Billiting	00106	Split System 50	DZ136SA0603AA/1501034114
32	22B91	1121025500 / 1121024300	TSC 50% - NO 50%	Telephone Office / Billiting	00106	Split System 50	DZ136SA0603AA/1501034115
33	22B91	1121025500	TSC 100%	POST Chapel	00108	Split System 1	3703E29605
34	22B91	1121025500	TSC 100%	POST Chapel	00108	Split System 2	38CK060371
35	22B91	1121025500	TSC 100%	POST Chapel	00108	Split System	3703E29519
36	22B91	1121025500	TSC 100%	POST Chapel	00108	Split System 3	38CL036351
37	22B91	1121025500	TSC 100%	POST Chapel	00108	Split System	3103E13478
38	22B91	1121024300	NO 100%	All Ranks Club	00117	Split System	4TTB3060A1000BA
39	22B91	1121024300	NO 100%	All Ranks Club	00117	Split System 1-01	4TTB3060A1000BA/9394NH85F
40	22B91	1121024300	NO 100%	All Ranks Club	00117	Split System 1-02	4TTB3060A1000BA/9394NNY5F
41	22B91	1123022100	T10 100%	YCP Classroom	00118	Split System 1	TCGD48S43S1A /WOB895740001
42	22B91	1123022100	T10 100%	YCP Classroom	00118	Split System 1	TCGD48S43S1A / WAO0657853
43	22B91	1123022100	T10 100%	YCP Classroom	00118	Split System 1	TCGD36543S1A / WON84998199
44	22B91	1123022100	T10 100%	YCP Classroom	00118	Split System 1	4TTR4024L1000BA / 20334LBAAF
45	22B91	1123022100	T10 100%	YCP Classroom	00118	Split System 1	YCJD2454151A / YCJD2454151A
46	22B91	1123022100	T10 100%	YCP Classroom	00118	Split System 1	4TTR4024L1000BA / 18214BFT3F
47	22B91	1123022100	T10 100%	YCP Classroom	00118	Split System 1	TCGD36543S1A / WON89676413
48	22B91	1121025500	TSC 100%	Training Building	00119	Split System 1-01	4TWR5060H1000AA/16504RFM2F
49	22B91	1121025500	TSC 100%	Training Building	00119	Split System 1-02	4TWR5060H1000AA/1719242B2F
50	22B91	1121025500	TSC 100%	Training Building	00119	Split System 1-03	4TWR5060H1000AA/17234PCN2F
51	22B91	1121025500 / 1123022100 / 1121024300	TSC 35.7% - T10 35.7% - NO 28.6 %	YCP Activity Bldg / Exchange	00120	Split System 1	TTA180E300AA/14345KJXTA

HVAC SHOPPING CART INVENTORY
WHOLE FACILITY
FY/SY26

52	22B91	1121025500 / 1123022100 / 1121024300	TSC 35.7% - T10 35.7% - NO 28.6 %	YCP Activity Bldg / Exchange	00120	Split System 2	TWA18043DAB01/20311364TA
53	22B91	1121025500 / 1123022100 / 1121024300	TSC 35.7% - T10 35.7% - NO 28.6 %	YCP Activity Bldg / Exchange	00120	Split System 3	38AUZA16A0A5A/2012U20550
54	22B91	1121025500 / 1123022100 / 1121024300	TSC 35.7% - T10 35.7% - NO 28.6 %	YCP Activity Bldg / Exchange	00120	Split System 4	TWA07243AAA02B5010/22521199YA
55	22B91	1121025500 / 1123022100 / 1121024300	TSC 35.7% - T10 35.7% - NO 28.6 %	YCP Activity Bldg / Exchange	00120	Split System 5	TWA07243AAA01/21031639YA
56	22B91	1121025500 / 1123022100 / 1121024300	TSC 35.7% - T10 35.7% - NO 28.6 %	YCP Activity Bldg / Exchange	00120	Refrigeration Unit #7	MHHX0300B/H0425518
57	22B91	1121025500 / 1123022100 / 1121024300	TSC 35.7% - T10 35.7% - NO 28.6 %	YCP Activity Bldg / Exchange	00120	Refrigeration Unit #8	MHHX0300B/T0ZC101704
58	22B91	1121025500 / 1123022100 / 1121024300	TSC 35.7% - T10 35.7% - NO 28.6 %	YCP Activity Bldg / Exchange	00120	Refrigeration Unit #9	LCH0022CBBCZA0200/T24B13155
59	22B91	1121025500 / 1123022100 / 1121024300	TSC 35.7% - T10 35.7% - NO 28.6 %	YCP Activity Bldg / Exchange	00120		LLH0005MBAC2A0200/T24D07446
60	22B91	1123022100	T10 100%	YCP Dispensary/ Cadre	00129	Split Unit 1-01	4TTR3048D1000AA / 10512S525F
61	22B91	1123022100	T10 100%	YCP Dispensary/ Cadre	00129	Split Unie 1-02	4TWA4060A3000AA / 19021YAB2F
62	22B91	1123022100	T10 100%	YCP Dispensary/ Cadre	00129	Radient Heater	HANGING HEATER #1
63	22B91	1123022100	T10 100%	YCP Dispensary/ Cadre	00129	Heat Exchanger	HANGING HEATER #2
64	22B91	1123022100	T10 100%	YCP Dispensary/ Cadre	00129	Heat Exchanger	HANGING HEATER #3
65	22B91	1123022100	T10 100%	YCP Dispensary/ Cadre	00129	Heat Exchanger	HANGING HEATER #4
66	22B91	1123022100	T10 100%	YCP Dispensary/ Cadre	00129	Split Unit 1-03	25HCE448A500 / R1019E297776
67	22B91	1123022100	T10 100%	YCP Dormitory	00130	Package Unit 1	YCH090C3HOBE / R48100047D
68	22B91	1123022100	T10 100%	YCP Dormitory	00130	Package Unie 2	YSC072F3ELA / 180210121L
69	22B91	1123022100	T10 100%	YCP Dormitory	00130	Package Unit 3	YSC048A3MA0BC / 246100125L
70	22B91	1123022100	T10 100%	YCP Dormitory	00131	Package Unit 1	TSC090H3EMA03 / 201911686L
71	22B91	1123022100	T10 100%	YCP Dormitory	00131	Package Unie 2	YSC048A2 / 245100051L
72	22B91	1123022100	T10 100%	YCP Dormitory	00131	Package Unit 3	YCH075C3L0BE / Z26101282D
73	22B91	1123022100	T10 100%	YCP Dormitory	00132	Package Unit 1	YSC090H3EHA03 / 193813138L
74	22B91	1123022100	T10 100%	YCP Dormitory	00132	Package Unie 2	YSC048A3RMA / 14610101D
75	22B91	1123022100	T10 100%	YCP Dormitory	00132	Package Unit 3	YSC072H3EMA02A00 / 190712753L
76	22B91	1123022100	T10 100%	YCP Dormitory	00133	Package Unit 1	YSC090H3EMA260 / 213210468L
77	22B91	1123022100	T10 100%	YCP Dormitory	00133	Package Unie 2	YSC07263 / 120911442L
78	22B91	1123022100	T10 100%	YCP Dormitory	00133	Package Unit 3	YSC048A3RMA L
79	22B91	1123022100	T10 100%	YCP Supply	00144	Mini Split 1-01	RX09AXVJU/K007395
80	22B91	1123022100	T10 100%	YCP Supply	00144	Mini Split 1-02	RX09AXVJU/K002775
81	22B91	1123022100	T10 100%	YCP Supply	00144	Mini Split 1-03	5MXS48TVJU / e013562
82	22B91	1121025500	TSC 100%	MP HQ	00158	Split System	4TTR6048J1000AA/16396M5R2F
83	22B91	1121025500	TSC 100%	GYM	00160	Split System	2TTA0060AQ3000AA
84	22B91	1121025500	TSC 100%	GYM	00160	Split System	180B3H0GA
85	22B91	1121025500	TSC 100%	GYM	00160	Reefer Unit	OR-530L4-2T-E/A02155914-0801
86	22B91	1121025500	TSC 100%	GYM	00160	Reefer Unit	OR-513MCP-2T/A02155414-0101
87	22B91	1121025500	TSC 100%	GYM	00160	Split System 1-02	KGB180S4BS1Y/5619A00515
88	22B91	1121025500	TSC 100%	H - Barracks	00161	Split System	TTA09043AAB01AR/20231278YA
89	22B91	1121025500	TSC 100%	H - Barracks	00161	Split System	H1RA090525H/W066922304
90	22B91	1121025500	TSC 100%	T - Barracks	00162	Split System	4TTA3042A3000BA/10163LH85F
91	22B91	1121025500	TSC 100%	T - Barracks	00162	Split System	4TTA3042A3000BA/10163LJ5F
92	22B91	1121025500	TSC 100%	T - Barracks	00162	Split System	4TTA3060A3000BA/10171KF02F
93	22B91	1121025500	TSC 100%	BOQ	00171	Split System	PUZ-A18NHA3/8003608T
94	22B91	1121025500	TSC 100%	BOQ	00171	Split System	PUZ-A18NHA3/91U00790B
95	22B91	1121025500	TSC 100%	BOQ	00171	Split System	PUZ-A18NHA3/91U00791B
96	22B91	1121025500	TSC 100%	BOQ	00171	Split System	PUZ-A18NHA3/91U00B10B
97	22B91	1121025500	TSC 100%	BOQ	00171	Split System	PUZ-A18NHA3/91U00807B
98	22B91	1121025500	TSC 100%	BOQ	00171	Split System	PUZ-A18NHA3/91U00809B
99	22B91	1121025500	TSC 100%	BOQ	00171	Split System	PUZ-A18NHA3/91U00808B
100	22B91	1121025500 / 1123022100	TSC 74% - T10 26%	MUDFAC (TRNG Site, YCP)	00181	Split System	TTA150E300AA
101	22B91	1121025500 / 1123022100	TSC 74% - T10 26%	MUDFAC (TRNG Site, YCP)	00181	Split System	TTA120E300AA
102	22B91	1121025500 / 1123022100	TSC 74% - T10 26%	MUDFAC (TRNG Site, YCP)	00181	Split System	CC-B-014-2-0-2/200912-CHCC01392
103	22B91	1121025500 / 1123022100	TSC 74% - T10 26%	MUDFAC (TRNG Site, YCP)	00181	Split System	TTA180B300FA/9072P3RAD
104	22B91	1121025500 / 1123022100	TSC 74% - T10 26%	MUDFAC (TRNG Site, YCP)	00181	Split System	TTA120E300AA/9455PSTAD
105	22B91	1121025500 / 1123022100	TSC 74% - T10 26%	MUDFAC (TRNG Site, YCP)	00181	Split System	TTA150B300FA
106	22B91	1121025500 / 1123022100	TSC 74% - T10 26%	MUDFAC (TRNG Site, YCP)	00181	Split System	TTA180B300FA/9102S3UAD

HVAC SHOPPING CART INVENTORY
WHOLE FACILITY
FY/SY26

107	22B91	1121025500 / 1123022100	TSC 74% - T10 26%	MUDFAC (TRNG Site, YCP)	00181	Split System	RZQ30MVJU/E000328
108	22B91	1121025500 / 1123022100	TSC 74% - T10 26%	MUDFAC (TRNG Site, YCP)	00181	Split System	RZQ30MVJU/E000256/E000256
109	22B91	1121025500 / 1123022100	TSC 74% - T10 26%	MUDFAC (TRNG Site, YCP)	00181	Split System	TTA18043DAB01AE/21171073TA
110	22B91	1121025500 / 1123022100	TSC 74% - T10 26%	MUDFAC (TRNG Site, YCP)	00181	Split System	TTA180B300FA/9081P50AD
111	22B91	1121025500	TS6 100%	RTI Billeting	00190	Split System	MUY GE09NA/0001275T
112	22B91	1121025500	TS6 100%	RTI Education/ ADMIN	00191	Split System	AK09NMUJJ/G005333
113	22B91	1121025500	TS6 100%	RTI Education/ ADMIN	00191	Split System	AK09NMUJJ/G005345
114	22B91	1121025500	TS6 100%	RTI GateHouse	00196	Split System	AK09NMUJJ/G005350
115	22B91	1121025500	TSC 50% - TS6 50%	EST Facility / RTI Classroom	00427	Package Unit #71	W60AC-A15APXXXJ/289M213916321-02
116	22B91	1121025500	TSC 50% - TS6 50%	EST Facility / RTI Classroom	00427	Package Unit #72	W60CS15B1R/031-P50003
117	22B91	1121025500	TSC 50% - TS6 50%	EST Facility / RTI Classroom	00427	Package Unit #73	W60CS15B1R/031-P50004
118	22B91	1121025500	TSC 50% - TS6 50%	EST Facility / RTI Classroom	00427	Package Unit #74	W60CS15B1R/031-P50002
119	22B91	1121025500	TSC 100%	RTI Building	00428	Package Unit #74	GWH36LB-D3DNA3E
120	22B91	1121023000	NO 100%	M1 GOHSEP State Warehouse	00631	Split System	YCH240E3L0AA/730101816D
121	22B91	1121023000	NO 100%	M1 GOHSEP State Warehouse	00631	Split System	YCH240E3L0AA/730101843D
122	22B91	1121024300	NO 100%	DVQ Conference Center	01124	Split System 1-01	GSX140421KC/1510267348
123	22B91	1121024300	NO 100%	DVQ Conference Center	01124	Split System 1-02	GSX140601KA/1510267348
124	22B91	1121024300	NO 100%	DVQ Conference Center	01124	Split System 1-03	GSX140421KC/1601111415
125	22B91	1121024300	NO 100%	DVQ Conference Center	01124	Split System 1-04	RXN18NMVJU
126	22B91	1121025500	TSC 100%	Classroom	01401	Rooftop Unit	LCA120H4BLY/5608L10068
127	22B91	1121025500	TSC 100%	Classroom	01401	Rooftop Unit	560BG01431
128	22B91	1121025500	TSC 100%	Classroom	01401	Rooftop Unit	KCA03654DN/5608G01431
129	22B91	1121025500	TSC 100%	Classroom	01401	Rooftop Unit	KCA03654DN/5608K05395
130	22B91	1121025500	TSC 100%	Classroom	01401	Rooftop Unit	KCA03654DN/5608G15912
131	22B91	1121025500	TSC 100%	Classroom	01401	Rooftop Unit	KCA03654DN/5608H2826
132	22B91	1121025500	TSC 100%	Classroom	01401	Rooftop Unit	KCA03654DN/5608K01215
133	22B91	1121025500	TSC 100%	Classroom	01401	Rooftop Unit	13CX02423002/5808E18395
134	22B91	1121025500	TSC 100%	Classroom	01401	Rooftop Unit	ML14XC1S024/1921H08523
135	22B91	1121025500	TSC 100%	Classroom	01401	Rooftop Unit	KCA03654DN/5608O1784
136	22B91	1121025500	TSC 100%	Shoebridge Building	01433	Split System 55	2TTA0060A3000AA/73856LP3F
137	22B91	1121025500	TSC 100%	Shoebridge Building	01433	Split System 56	2TTA0060A3000AA/6411L373F
138	22B91	1121025500	TSC 100%	Shoebridge Building	01433	Split System 57	MULTI36HB230V1C0/63229976398
139	22B91	1121025500	SC8 100%	UTES (M) Maint Shop	01454	Package Unit #15	4TXM6518A1020CA/170604180X
140	22B91	1121025500	SC8 100%	UTES (M) Maint Shop	01454	Package Unit #15	4TXM6542A1050CB/170202406X
141	22B91	1121025500	SC8 100%	UTES (M) Maint Shop	01454	Package Unit #15	4TXM6524A1080CA/170603443X
142	22B91	1121025500	SC8 100%	UTES (M) Maint Shop	01454	Package Unit #15	4TXM6536A1040CB
143	22B91	1121025500	TSC 100%	Forestry Building	01472	Split System 58	4TXM6542A1050CB/170202432X
144	22B91	1121025500	TSC 100%	Forestry Building	01472	Split System 58	4TXM6542A1050CB/170202460X
145	22B91	1121025500 / 1121024300	TSC 50% - NO 50%	Sewer Treatment Plant	02000	Split System 1-01	GWH30LB-D3DNA3E
146	22B91	1121025500 / 1121024300	TSC 50% - NO 50%	Sewer Treatment Plant	02000	Split System 1-02	MPB012S4S-1L/56917C19473
147	22B91	1121025000 / 1121024300	S15 35% - NO 65%	RC Det 1 CoB / State Warehouse	02629	Package Unit(s)	50TFF006-A-511/3805G30251
148	22B91	1121025000 / 1121024300	S15 35% - NO 65%	RC Det 1 CoB / State Warehouse	02629	Package Unit(s)	50TFF005-A-511/3505G50290
149	22B91	1121025000 / 1121024300	S15 35% - NO 65%	RC Det 1 CoB / State Warehouse	02629	Package Unit(s)	EBC048A3E0B05/20272646PA
150	22B91	1121025000 / 1121024300	S15 35% - NO 65%	RC Det 1 CoB / State Warehouse	02629	Package Unit(s)	TTA090A300FA/809437AAD
151	22B91	1121025500	TSC 100%	Scale House Gate 4	05106	Split System 1-02	W60A1-A10/324K122941789-02
152	22B91	1121025500	TSC 100%	Fire Station	05114	Split System 1	GSX140601KD/2001074930
153	22B91	1121025500	TSC 100%	Fire Station	05114	Split System 2	HS18-511-5P
154	22B91	1121025500	TSC 100%	Guard House GATE # 3	05115	Split System 59	VSZ140361AE/1712141681
155	22B91	1121024300	NO 100%	Staff Housing	100CD	Split System	24ABC630A300 / 4313E05799
156	22B91	1121024300	NO 100%	Staff Housing	101CD	Split System	24ABC636A300 / 5012E0881
157	22B91	1121024300	NO 100%	Staff Housing	102CD	Package Unit 40A	4TTR4036L1000AA/144110GLAF
158	22B91	1121024300	NO 100%	Staff Housing	106CD	Package Unit 34A	GSX140361KG/2111208127
159	22B91	1121024300	NO 100%	Staff Housing	107CD	Split System	24ABC636A300 / 4613E10196
160	22B91	1121024300	NO 100%	Staff Housing	109CD	Split System	24ABC636A300 / 5012E2786
161	22B91	1121024300	NO 100%	Staff Housing	112CD	Package Unit 37A	HAC060AKA2

HVAC SHOPPING CART INVENTORY
WHOLE FACILITY
FY/SY26

162	22B91	1121024300	NO 100%	Staff Housing	119CD	Mobile Home Splits	GSX140361KG/2111208131
163	22B91	1121024300	NO 100%	Staff Housing	121CD	Package Unit 44A	GSX140361KG/2111203164
164	22B91	1121024300	NO 100%	Staff Housing	123CD	Mobile Home Splits	TC4B362Z5A/WZG1250108
165	22B91	1121024300	NO 100%	Staff Housing	125CD	Mobile Home Splits	AG036X1021A
166	22B91	1121024300	NO 100%	Staff Housing	133CD	Package Unit 39A	AC036Y1021A
167	22B91	1121024300	NO 100%	Staff Housing	138CD	Split System	24ABC636A300 / 3913E04704
168	22B91	1121024300	NO 100%	Staff Housing	140CD	Split System	24ABC630A300 / 1613E04460
169	22B91	1121024300	NO 100%	Staff Housing	142CD	Split System	24ABC636A300 / 5012E08848
170	22B91	1121024300	NO 100%	Staff Housing	144CD	Split System	24ABC630A300 / 3913E10579
171	22B91	1121024300	NO 100%	Staff Housing	145CD	Split System	24ABC636A300 / 3713E14821
172	22B91	1121024300	NO 100%	Staff Housing	146CD	Split System	24ABC636A300 / 3613E14277
173	22B91	1121025500	TSC 100%	UOQ	00172	Fresh Air Handler	DPS004AHMGZPW / FBOU220900201
174	22B91	1121025500	TSC 100%	UOQ	00172	Split System	FTXS09LVJU / E219080
175	22B91	1121025500	TSC 100%	UOQ	00172	Split System	FTXS09LVJU / E221381
176	22B91	1121025500	TSC 100%	UOQ	00172	Split System	FTXS09LVJU / E219069
177	22B91	1121025500	TSC 100%	UOQ	00172	Split System	FTXS09LVJU / E219072
178	22B91	1121025500	TSC 100%	UOQ	00172	Split System	FTXS09LVJU / E220233
179	22B91	1121025500	TSC 100%	UOQ	00172	Split System	FTXS09LVJU / E219068
180	22B91	1121025500	TSC 100%	UOQ	00172	Split System	FTXS09LVJU / E221367
181	22B91	1121025500	TSC 100%	UOQ	00172	Split System	FTXS09LVJU / E219121
182	22B91	1121025500	TSC 100%	UOQ	00172	Split System	FTXS09LVJU / E221374
183	22B91	1121025500	TSC 100%	UOQ	00172	Split System	FTXS09LVJU / E220243
184	22B91	1121024300	NO 100%	State Billiting	BG-5	Split System 1-01	RXB24AXVJU/K004885
185	22B91	1121024300	NO 100%	State Billiting	BG-5	Split System 1-02	RXB24AXVJU/K004185
186	22B91	1121024300	NO 100%	State Billiting	BG-5	Split System 1-03	RXN24NMVJU/
187	22B91	1121024300	NO 100%	State Billiting	BG-5	Split System 1-04	RXB24AXVJU/K004189
188	22B91	1121024300	NO 100%	State Billiting	BG-5	Split System 1-05	RXB24AXVJU/K004191

Each dated preventive maintenance intervention consist of the following activities:
Cleaning, aligning, calibrating, tigtening, adjusting, lubricating and testing. Each dated
intervention will also represents filter change date.