



McNEESE
STATE UNIVERSITY
A Member of the University of Louisiana System

PURCHASING DEPARTMENT
 P. O. BOX 92415
 LAKE CHARLES, LA 70609
 PH: 337-475-5083
 FAX: 337-475-5082

ADDENDUM 01

DATE: November 5, 2024

BID #D2500037 to Replace and Repair Security Cameras
SCHEDULED TO OPEN ON NOVEMBER 11, 2024 AT 2 :00 P.M.

 REVISIONS TO THE REFERENCED SOLICITATION/BID AS STATED BELOW:

- **THE USE OF BRAND NAME IS FOR THE PURPOSE OF DESCRIBING THE STANDARD OF QUALITY, PERFORMANCE, AND CHARACTERISTICS DESIRED AND IS NOT INTENDED TO LIMIT OR RESTRICT COMPETITION. IF YOU ARE RETURNING A BID ON AN ITEM THAT IS EQUAL, YOU MUST INCLUDE THE BRAND NAME, ITEM OR SKU NUMBER AND SPECIFICATIONS WITH YOUR BID RESPONSE.**
- **SEE ATTACHED QUESTIONS AND OR REQUESTS WITH RESPONSES TO INQUIRIES.**
- **ALL OTHER SPECIFICATIONS, BID DUE DATE AND TIME REMAIN THE SAME.**

 THIS ADDENDUM IS HEREBY OFFICIALLY MADE A PART OF THE REFERENCED SOLICITATION FOR BID.

ACKNOWLEDGEMENT: If you have already submitted your bid and this Addendum does not cause you to revise your bid, you must acknowledge receipt of this Addendum by identifying your business name and by signing where indicated. You may return this Acknowledgement with your bid or fax to (337)475-5082 or email to debet@mcneese.edu or mail to the address above. The State reserves the right to request a completed Acknowledgement at any time. Failure to execute an Acknowledgement shall not relieve the bidder from complying with the terms of its bid.

Addendum Acknowledged / No Changes:

VENDOR NAME: _____

Signature: _____ Print: _____

I APOLOGIZE FOR ANY INCONVENIENCE THIS MAY HAVE CAUSED.

DEBET HEBERT
 PROCUREMENT SPECIALIST
 McNeese State University

BID D2500037 – ADDENDUM 1 ATTACHMENT

QUESTIONS/REQUESTS AND RESPONSES:

1. Are there any CCTV or Conduit plans from when the structure was built that you can provide?

Response: The type of plans requested is unavailable.

2. Cable lengths and cable type for various line items needing replacing.
 - a. Line item 1 – 137 feet, Cat6.
 - b. Line item 4 – length being “unknown” is because that cable has been damaged and showed fault in the line. The test results is “Unknown length”, which is why the cable needs to be replaced.
 - c. Line item 14 – 407 feet.
 - d. Line item 15 – 218 feet cable pull, Cat6.
 - e. Line item 16 – 457 feet.
 - f. Line item 17 – 457 feet.
 - g. Line item 18 – 451 feet.

3. Requests for construction drawings/building layouts with camera locations for the parking garage that identifies wire runs, pull boxes, and camera locations.

Response: The type of drawings requested is unavailable.

4. Do you need a new server? If so what capacity and how many?

Response: No new server is required.

5. Do we need to incorporate lift or will one be provided by the school?

Response: A lift will be provided by the University.

6. Are we providing PoE switches?

Response: PoE switches are already in place. None need to be provided.